


METAL EARTH[®]


3D METAL MODEL KITS

360°
view

It is highly recommended that you visit
www.fascinations.com/metalearth360/mms295
 to see the completed model before assembling your own




mms295



Insertion tabs are inserted and then folded

Insertion holes

Fold lines can be seen as shown here



Legends:

E Engraved side


NE Non-engraved side

Attention point


To create the best connections

Insert tab and bend 90 degrees for most visible areas

Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



Metal sheets



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

