METALEARTH


3D LASER CUT MODELS




It is highly recommended that you visit

www.fascinations.com/metalearth360/mms007
to see the completed model before assembling your own







Insertion tabs are inserted and then folded Fold lines can be seen as shown

Insertion holes

Needle nose pliers are helpful for assembly

Metal sheet

To create the best connections


here




Insert tab and bend 90 degrees for most visible areas



Insert tab and twist 90 degrees is best in some areas to ensure a tight connection







In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

